



DEST AVAILABLE CO






BEST AVAILABLE COPY




BEST AVAILABLE COPY



Replacement Sheet



SEM Micrograph of Group B at 300x after Electrochemical Test.



SEM Micrograph of Group B at 700x after electrochemical test.

Fig. 6A

Fig. 6B




Fig. 7A




Fig. 7B

SEM micrographs of the Hayes CrCoMo sample after ASTM F746 corrosion test indicates intergranular corrosion attacks.



Replacement Sheet




Fig. 7C




Fig. 7D

SEM micrographs of the Hayes CrCoMo sample after ASTM F746 corrosion test exhibiting corrosion attacks.

BEST AVAILABLE COPY



Replacement Sheet




Fig. 8A




Fig. 8B

SEM micrographs of the Hayes CrCo sample prior to any corrosion test.